<u>MSO8104A-03</u> <u>S E R V I C E N O T E</u>

Supersedes: NONE

MSO8104A 1 GHZ 4 CH Infiniium Oscilloscope

Serial Numbers: MY45001900 and below, SG45001900 and below

The purpose of this Service Note is to notify service personnel that the original CPU PCA assembly has been replaced in these affected units. This new CPU PCA assembly is compatible with the old assembly.

Part number D81004-68809 has been replaced by part number 0960-2652.

Parts Required:		
P/N	Description	Qty.
0960-2652	CPU PCA assembly - Micro ATX 915GHZ	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: MR PRODUCT LINE: PL1A

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.





June 1, 2007

Situation:

Service Manual D8064-970002 still reflects old part number for field replacement.

Solution/Action:

Use part number 0960-2652 for motherboard replacement.