N5193A-01B

Modification Recommended Service Note

Supersedes: N5193A-01A

N5193A -UXG X-Series Agile Signal Generator

Serial Numbers: see list last page

The Problem – N5193A service notes are classified as technical data. Service notes related to this product are store on the US Domain / Share point folder

Parts Required:

P/N Description Qty.

N5191-60153 Power supply

ADMINISTRATIVE INFORMATION

ACTION	[]] ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	[X] AGREEABLE TIME	LABOR: 1.0 Hours			
LOCATION CATEGORY:	X SERVICE CENTER [[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [X] SCRAP [[]] SEE TEXT			
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 07 January 2025			
[[]] Calibration Required X Calibration NOT Required		PRODUCT LINE: 15 AUTHOR: MW			

ADDITIONAL INFORMATION:



Situation:

N5193A service note are classified as technical data. Service notes related to this product are store on the US Domain / Share point folder

Solution/Action:

- 1) obtain US Domain access
- 2) After obtaining US Domain log in and unique password
- 3) View N5193A Service notes at https://keysight.sharepoint.us/documents/servicenotes

Revision History:

Date	Service Note Revision	Author	Reason for Change
18 Sept 2018	01	SN	As Published
02 Oct 2018	02	SN	Add Contact division
07 Jan 2022	03	MW	Extend No Charge available to 07 Jan 2025