# N5230C-02 S E R V I C E N O T E

Supersedes: NONE

# N5230C PNA Microwave Network Analyzers

Serial Numbers: US00000000/US999999999 (ALL)

During System Verification test, N5230C analyzers that encounter errors while measuring the verification kit devices should upgrade to the most recent firmware and retry the test.

Parts Required:P/NDescriptionNONE

Qty.

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: MF	PRODUCT LINE: WN
ADDITIONAL INFORMATION: Affected PNA models: E8361/2/3/4C and N5230C. Service Note history: N5230C-02 written August 31, 2009.	

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



#### N5230C-02

## Page 2 of 2

#### Situation:

During System Verification test, some N5230C analyzers are experiencing errors while measuring the verification kit devices.

### Solution/Action:

Download the most recent firmware and retry the test.