

N5242A-03A

# Information Only Service Note

Supersedes:  
N5242A-03

## N5242A PNA Series Microwave Network Analyzers

Serial Numbers: ALL

Manufacturing ID Number: N/A

A group of front panel assembly items have had part number changes (see next page). If you replace the old part number of any item in the group with its new part number, you must also replace ALL of the other old part numbers in the group with their new part numbers too.

### Parts Required:

P/N	Description	Qty.
N5240-60065	Front panel interface board	1
N5242-40009	Touch screen rubber boot	1
2090-1045	Touch screen, 10.4 inch	1
0960-3063	Touch screen controller board	1
W1312-60047	Touch screen controller board cable harness	1
N5245-00027	LCD display hold down bracket	1

### ADMINISTRATIVE INFORMATION

PRODUCT LINE: WN  
AUTHOR: KS

#### ADDITIONAL INFORMATION:

Affected PNA models: N5242A and N5242AH85.

Service Note History: N5242A-03A released 9/11/15.

**Situation:**

A group of front panel assembly items have had part number changes (see next page). If you replace the old part number of any item in the group with its new part number, you must also replace ALL of the other old part numbers in the group with their new part numbers too.

**Solution/Action:**

Replaced PNA old part numbers with the new part numbers.

**Revision History:**

Date	Service Note Revision	Author	Reason for Change
31 March 2009	01	Mac Freeman	As Published
08 September 2015	02	Keith Stengl	Part numbers have changed: N5240-60065, 2090-1045, 0960-3063, and N5245-00027.