

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

N8974A-05

S E R V I C E N O T E

Supersedes:
None

N8974A Noise Figure Analyzer

Serial Numbers: All

A8 RF assembly replacement part numbers

Parts Required:

P/N	Description	Qty.
None		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: [initials] PRODUCT LINE: [product line]
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2006
PRINTED IN U.S.A.



November 29, 2006

Situation:

This service note is to clarify the part numbers to be used for the A8 RF assembly for the NFA's.

Solution/Action:

Following are the RF assemblies that should be used for NFA depending on whether the instrument has option 1D5 or does not have option 1D5.

N8972A and N8973A

- Without option 1D5:
N8972-60012 or exchange N8972-69012
- With option 1D5
N8972-60013 or exchange N8972-60013

N8974A and N8975A

- Without option 1D5
N8974-60012 or exchange N8974-60012
- With option 1D5
N8974-60013 or exchange N8974-60013