## INFORMATION ONLY

N9UZUA-U <sup>2</sup>	0A-04	0	2	0	9	N	I
-----------------------	-------	---	---	---	---	---	---

# S E R V I C E N O T E

Supersedes: NONE

N9020A MXA Signal Analyzer

Serial Numbers: ALL

A26 Wideband Digital IF Assembly Requires Instrument Software Upgrade

The A26 Wideband Digital IF Assembly, p/n N9020-60257, requires SW revision A.13.12 or later.

Parts Required:

P/N Description Qty.

NONE

### **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:					
INFORMATION ONLY					
[[]] Calibration Required	PRODUCT LINE: 12				
X Calibration NOT Required	AUTHOR: BS				
ADDITIONAL INFORMATION:					

© AGILENT TECHNOLOGIES, INC. 2014 PRINTED IN U.S.A.



June 20, 2014

Rev. 22

Page 2 of 2 N9020A-04

#### Situation:

The A26 Wideband Digital IF Assembly, p/n N9020-60257 was introduced in June 2014, and because of some circuit changes, a minimum software revision is required when installing this assembly. This Wideband Digital IF Assembly is only present on instruments with option B1A, B1X or B85. Instrument specifications are unchanged.

#### Solution/Action:

The Instrument software must be revision A.13.12 or later for the Wideband Digital IF Assembly to function.

The latest N9020A MXA software can be down loaded for <a href="www.agilent.com/find/xseries">www.agilent.com/find/xseries</a> software

**Revision History:** 

Revision Number	Date	Author	Reason For Change
1.0	6/20/2014	BS	As published