# U1211A-01 <u>S E R V I C E N O T E</u>

Supersedes: NONE

## U1211A Handheld Clamp Meter

Serial Numbers: MY53080002

U1211A unit missing calibration traceability

Parts Required:

P/N Description Qty.

**NONE** 

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION X ON SPECIFIED FAILURE CATEGORY: [[]] AGREEABLE TIME	STANDARDS  LABOR: 1 Hour			
LOCATION [[]] CUSTOMER INSTALLABLE CATEGORY: [[]] ON-SITE (active On-site coverage only)  X SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT  USED [[]] RETURN PARTS: [[]] SCRAP [[]] SEE TEXT			
AVAILABILITY: PRODUCT'S SUPPORT LIFE	RODUCT'S SUPPORT LIFE NO CHARGE AVAILABLE UNTIL: 6 November 2014			
X Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: WC AUTHOR: SJ			
ADDITIONAL INFORMATION:				

© AGILENT TECHNOLOGIES, INC. 2013 PRINTED IN U.S.A.



November 6, 2013

Rev. 21

Page 2 of 2 U1211A-01

#### **Situation:**

During recent Agilent internal process audit, it is discovered that the test result file of the unit identified by serial number listed above could not be located in the database. Therefore Agilent would like to proactively withdraw the unit back for verification calibration and for traceability purposes.

#### **Solution/Action:**

Please contact the nearest Agilent Service Centre for calibration request by quoting this service note.

#### **Revision History:**

Revision Number	Date	Author	Reason For Change
1.0	11/6/13	SJ	As published
_			