U1604A-03

SERVICE NOTE

Supersedes: NONE

U1604A Handheld Oscilloscope

Serial Numbers: KR5000000 - KR50329999

BNC cable cannot secure oscilloscope input channel

Parts Required:

P/N	Description	
U1604-69002	Exchanged – Refurbished	1
U1604-66002	Exchanged – New	1
U1604-66003	Exchanged (USB) – New	1
U1604-69003	Exchanged (USB) – Refurbished	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION CATEGORY:	X ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 0.1 Hours		
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE X RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT	USED X RETURN PARTS: [[]] SCRAP [[]] SEE TEXT	
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 30 June 2013		
AUTHOR: TY		PRODUCT LINE: WC		
ADDITIONAL INFORMATION: Only applicable for serial number range above.				

© AGILENT TECHNOLOGIES, INC. 2010 PRINTED IN U.S.A.



September 27, 2010

Rev. 17

Page 2 of 2 U1604A-03

Situation:

If customer report about BNC connection cannot lock at Handheld Oscilloscope BNC connect. Please refer to picture below:







Solution/Action:

- 1. Verify customer unit with Agilent BNC cable or Agilent BNC connector (1250-0256)
- 2. If verification failed, please provide unit exchange with customer.
- 3. If verification passed, please inform customer the BNC connector is meeting spec and no action required from SSU.