S E R V I C E N O T E

SUPERSEDES: NONE

4194A Impedance/Gain-Phase Analyzer

Serial Numbers: 0000J00000 / 2617J01520

Updated CRT display repair parts list for the older 4194A

Duplicate Service Notes: None

To Be Performed By: Agilent-Qualified Personnel

Situation:

- 1. Some part numbers were changed from what listed in the 4194A Service Manual.
- 2. Some parts are discontinued, and are supplied from the limited stocks.

Solution/Action:

1. Correct the parts list in the 4194A Service Manual page 6-153. The table below shows the whole part numbers, and asterisks(*) denote the changes.

Continued

DATE: 09 September 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY				
3355				
	INFORMA ENTITY:			

© 1992 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 4194A-11

Ref. Des.	Part No.	Qty.	Description
1	2100-4118	1	R Variable, INTENSITY
	04194-61628	1	Cable Assembly, INTENSITY
2	04194-61632	1	Coil Assembly, Degausser
3	04194-04004	1	Cover for A17 Board Assembly
4	04194-04002	1	Cover for A4 Board Assembly
5	04194-04003	1	Cover for A5 Board Assembly
6	04194-64906*	1	CRT Assembly
7	04194-64907*	1	H.V. Block Assembly (HVR and FBT)

2. When the faulty part cannot be isolated, or when any parts above run out, replace the whole display assembly (which incudes PC boards and all the items listed above) with a new assembly. The part number is as follows:

Part No.Description04194-64908CRT Display Assembly